

of the Borough President of the Borough of Manhattan,

In The City of New York.

BUREAU OF BUILDINGS FOR THE BOROUGH OF MANHATTAN

Office, No. 220 FOURTH AVENUE,
S. W. Corner 18th Street.

PLAN No.

1661

NEW BUILDING
ALTERATIONS

1905

Location

276 E. 3rd Street

BOROUGH OF MANHATTAN.

In all cases Inspectors will furnish the following information without regard to the information given in the application and plans on file in the Bureau.

1. Foundation walls. Depth below curb level _____ material _____
thickness, front _____ inches; rear _____ inches; side _____ inches; party _____ inches.

2. Upper walls. Material _____; thickness as follows:
Basement: front _____ inches; rear _____ inches; side 16" inches; party _____ inches
1st story: " " " " " 12 " " "
2d story: " " " " " 12 " " "
3d story: " " " " " 12 " " "
4th story: " " " " " 12 " " "
5th story: " " " " " 12 " " "
6th story: " " " " " _____ " " "

3. Nature of ground. _____

4. Quality of sand used in mortar _____

5. What walls are built as party walls? _____

6. What fire escapes are provided? _____

7. Is building fireproof? 1

8. If building is vacant, state how the same was occupied _____

9. Is the present building to be connected with any adjoining building? _____

If so, state dimensions and material of adjoining building, viz:—

Material _____; feet front _____, feet rear _____

feet deep _____; feet in height _____; number of stories _____

how occupied _____

10. How is present building occupied? Basement Baking; 1st floor store & 1 room;

2d floor 4 rooms; 3d floor 4; 4th floor 4; 5th floor 4;

6th " _____; 7th " _____; 8th " _____; 9th " _____;

11. Height of building—feet 52; stories 5

12. Size of building—feet front _____; feet rear _____; feet deep _____

13. Size of lot— " " _____; " " _____; " " _____

14. Are fireproof shutters provided? _____ What kind? _____

William L. Kirill

Inspector.

Dated,

June 29 1905